

Pemberton Township Schools
Drinking Water Analytical Reports Table

As of January 31, 2017, all initial results for lead water testing for the Busansky, Emmons, Harker-Wylie, Stackhouse, Denbo, Crichton, PECEC, Helen Fort, Newcomb, Fort Dix and PTHS school buildings was completed. Results from Haines and the adjacent TCU were received September 18, 2017 and are included in the chart. The last column will be filled in when Final Action is complete.

The following locations were identified as having lead levels at or exceeding the state allowable action levels. All other outlets have tested below the allowable action level of 15 µg/1 (parts per billion [ppb]).

#	Sample Location	Draw Results ug/1 (ppb)	Interim Remedial Action Taken	Basis/Follow-up	Final Action
1	Samuel Busansky Elementary Media Center workroom sink	21.3	Taken out of service – supply line turned off	Fixture slated for immediate replacement/retest	Permanent Sign: "Not for Drinking" placed over sink; back in service
2	Isaiah Haines Building (Building currently not in use) Nurse's Office Sink	19.8	Taken out of service – supply line turned off	Fixture slated for immediate replacement/retest	Replacement Completed, Retested: <1.0 Back in Service
3	Helen Fort/Newcomb MS HELEN FORT BUILDING Room 55 Science Lab Sink Not typically used for drinking water	22.2	Signage posted stating unsafe for drinking	Fixture slated for immediate replacement/retest	Permanent Sign: "Not for Drinking" placed over sink; back in service
4	Helen Fort/Newcomb MS HELEN FORT BUILDING Art Room Sink Not typically used for drinking water	15.2	Signage posted stating unsafe for drinking	Fixture slated for immediate replacement/retest	Permanent Sign: "Not for Drinking" placed over sink; back in service
5	Helen Fort/Newcomb MS HELEN FORT BUILDING Room 48 Science Lab Sink Not typically used for drinking water	15.4	Signage posted stating unsafe for drinking	Fixture slated for immediate replacement/retest	Permanent Sign: "Not for Drinking" placed over sink; back in service
6	Helen Fort/Newcomb MS HELEN FORT BUILDING Art Room Sink Not typically used for drinking water	18.4	Signage posted stating unsafe for drinking	Fixture slated for immediate replacement/retest	Permanent Sign: "Not for Drinking" placed over sink; back in service
7	Fort Dix Elementary School Kitchen Ice Machine	77.0	Taken out of service – supply line turned off	Plumbing slated for immediate replacement/retest	Replacement Completed, Retested: <1.0 Back in Service
8	Helen Fort/Newcomb MS NEWCOMB BUILDING Kitchen Ice Machine	490.0	Taken out of service—supply line turned off	Plumbing slated for immediate replacement/retest	Replacement Completed, Retested: <1.0 Back in Service

-Continued-

#	Sample Location	Draw Results ug/1 (ppb)	Interim Remedial Action Taken	Basis/Follow-up	Final Action
9	Helen Fort/Newcomb MS NEWCOMB BUILDING Water fountain by Room 312	16.0	Taken out of service—supply line turned off	Fixture has been permanently disabled	Fixture has been permanently disabled
10	PTHS B-Side Kitchen Steamer Sink	34.0	Taken out of service—supply line turned off	Faucet has been replaced/will be retested	Replacement Completed, Retested: <1.0 Back in Service
11	PTHS B-Side Kitchen Water Fountain	49.0	Taken out of service—supply line turned off	Fixture has been permanently disabled	Fixture has been permanently disabled
12	PTHS A-Side Drafting Sink Not typically used for drinking water	69.0	Signage posted stating unsafe for drinking	Signs will remain posted permanently.	Permanent Sign: “Not for Drinking” placed over sink; back in service
13	PTHS A-Side Water Fountain in Auditorium Lobby	30.0	Taken out of service – supply line turned off	Fixture slated for immediate replacement/retest	Replacement Completed, Retested: 8.1 Back in Service